

Title: Fade controller for providing programmable fade

rates for on-screen display (OSD) window

Inventor: Mohammad K. Seth

Appl.No. 10/614,228 Atty.Docket No.: P05617




FIG. 1





FIG. 2

Title: Fade controller for providing programmable fade

rates for on-screen display (OSD) window

Inventor: Mohammad K. Seth

Appl.No. 10/614,228 Atty.Docket No.: P05617



Title: Fade controller for providing programmable fade rates for on-screen display (OSD) window Inventor: Mohammad K. Seth Atty.Docket No.: P05617 Appl.No. 10/614,228 102 103b IDLE 103a-JS H accum = hintvl !A 104 -105b H_accum = H_accum+hintvl FIW4A 105a H_count = H_accum 112 ١V 10 107c 106 -113b -107b FIW4V FIW40 113a 107a O H count = H_acount-1 !TC 108--109b **FICNT** H_count = H_accum 109a H accum = H_accum-hintvl 110 -111b FIW4H 10 111a 109c 114 !FOA 115c -115b **VDN** W4FO 102 .115a **FOA** H_accum = 10 **IDLE** H_accum - hintvl 117c -117b 116 **FOW40** 123c-H count = H_count-1 117a O H_count = H_accum !TC 118 123b 119b 122 **FOCNT !H** 123d 119a TC FOW4V 121b 120 123a **OVR II VDN** FOW4H !FOE 121a 125a **FOE** 102 -125b **IDLE FOEND** 124

 $A = active_1$

FIE = FEN & OSD_ENABLE & Window1_Enable

FOE = FEN & (OSD_ENABLE | WINDOW1_ENABLE)

FOA = FOE & A

100

!H

H = Win1_is _on (set on start of Win1 & cleared on line_beg-le Or start of Win2)

O = H & OSD_ON

FI = FEN & O

OVR = h accum - HINTVL <= 0

S = FIE & V & HINTVL = 0TC = h count to V = vflyback_sl & line_beg_le VDN = Vertical Fade Out Done

FIG. 4

Title: Fade controller for providing programmable fade

rates for on-screen display (OSD) window

Inventor: Mohammad K. Seth

Appl.No. 10/614,228 Atty.Docket No.: P05617

